HABS NH 8 SAND

١.-

PHOTOGRAPHS AND DESCRIPTIVE DATA District of New Hampshire

Historic American Buildings Survey Eugene W. Clark, Deputy Officer Durham, New Hampshire

HABS

8- SAND.

L

MEETING HOUSE Sandown, Rockingham County New Hampshire

Owner

A group of townspeople.

Date of Erection

1773-4.

Architect

Unknown

Builder

Unknown

Present Condition

Excellent. Except that the upper portion of first floor pews with section containing the spindles has been removed the Meeting House is practically as originally built and is well cared for.

Number of Stories

Two.

Materials of Construction

Stone foundations. Superstructure is wood. Clapboard exterior finish. Shingle roof. Interior plastered between major members of construction.

Other Existing Records

Occasional photographs. Sandown Town Book.